1/2/14

INDEX

AME : _____ STD. : _____ SEC. : _____ ROLL NO. : _____

No.	Date	Title	Page No.	Teacher's Sign / Remarks
1)		Name of work :- Maintenance BBMP Drilled B.W. in Ward No. 09 of Vidyaranyapura Sub-Division.		
2)		Estimated cost :- 5.00 Lakhs		
(3)		DD. No :- 009-14-000028		
(4)		Work order. No :- EE/BAP/BBMP/T-Proj/16/1130/WO/328/13-14 Dt. 13-02-2014		

ulation

seal

D:1. 24/2/14

Dodlabomasandra main road. in front of Bakery.

Ward no: 9.

Workdone:-

1) Transportation of pumping machineries.
2) Labour charges
3) Rewinding of Submersible pumpset with copper insulation wire
4) ~~Installation~~ of 10Hp & 1~~2~~50 Hp motor. repair
5) Repair of starters and Rotor.
6) Repair of its upper flange.
7) Lower housing as per the direction of Engineer.
8) Carbon housing.
9) Thrust bearing block assembly.
10) Replacement of pump parts like oil seal ~~etc~~; oil seal steel bush, Guide value.
11) Impeller shell moulded with aluminium Bronze complete
12) Discharge outlet Bearing, Do steel bush,
13) Replacement of Brass filter.
14) cable guard replaced.

K. Nandini 9964096576.

ನವೀನ 9742927899

ಸಂತೋಷ್ 9902828359

~~ಮಂಜು~~

ಮಂಜುನಾಥ್ 6991443 8

24/02/2014

Bullet Krishnappa layout near Beriyan tree :- near doctor house, Ward no: 9.

Dt 8/3/14

Work done:-

1) Transporting pump machines.
2) Rewinding of pumpset.
3) 10HP & ~~10 S~~HP motors.
4) starter & Rotors.
5) upper flange
6) carbon * & lower housing.
7) Thrust bearing block assembly
8) oil seal steel bush
9) Guide value.
10) discharge outlet Bearing & DO steel bush.
11) pump shaft
12) Non return value.
13) cable guard
14) Brass - filter.
15) Coil overhauling and painting.
16) Insulation with copper.

ನಂಜಪ್ಪ

9611874666

9035446644

9986071801

9986635520

ಎಸ್.ಡಿ.ಓ 2.

Basavaraj

AE W-9 8/3/14

Thindlu near. Samudayas Bhavan Ward no: 9.

Dt. 29/03/14

Work done:-

1) Labour charge.
2) Rewinding of pumpset.
3) Transportation.
4) ~~10 HP~~ 12.5HP & ~~12.5HP~~ motor
5) upper flange.
6) Lower & Carbon housing.
7) starters & rotaters
8) Thrust bearing block assembly.
9) oil seal steel bush & Quick valve of pump.
10). DO Bearing, DO steel bush.
11) & Impeller shell
12) pump shaft and Non return valve.
13) Cable guard, Brass filter.
14) Overhowling and painting.
15) Insulation using copper.

Bhagya

~~ಭಾಗ್ಯಶೆಟ್ಟಿ~~

~~ನಾಗರಾಜ~~

Nagaraj

55531 49586.

9760589884

9980569144

9844300388

29/03/14

AE
Ward no. 09

Thindlu gowdar beedi. Ward no: 9.

Dt 24-04-2014

Workdone:-

1) 10HP & ~~10 5HP~~ motor.
2) Transportation.
3) labour charge.
4) Rewinding of submersible pumpset
5) starter & Rotors.
6) upper flange.
7) Lower & carbon housing.
8) Thrust bearing block assembly.
9) oil seal steel bush & Guide value.
10) Impeller shell moulded ಮಾ
11) DO Bearing, Do steel bush.
12) pump shaft
13) non-return value., cable guard.
14) Brass-filter.
15) overhauling & painting.
16) Insulation.

N. G. Umesh 9742337163

ರಮೇಶ 8453242029

Vijaya Lakshmi 9845444002.

ಮಂಜುನಾಥ 7760589884

Manjunatha 9845861088

24/04/2014

W.O.S

Bullet Krishnappa layout near. Satya green apartment :-
ward no 9.

Dr. 28-04-2014

Workdone

1) Insulation using copper.
2) Bran-filter.
3) overhauling & pointing
4) pump shaft, Non return valve.
5) Cable guard.
6) Impeller shell moulded.
7) DO Bearing, Do steel bush.
8) oil seal steel bush, Guide valve.
9) Thrust bearing block assembly.
10) Carbon & lower housing
11) Transportation of machineries.
12) upper flange
13) starter & Rotors
14) ~~[illegible]~~ 12.5 Hp motor.
15) labour charge.

Bagavnelara — 9900218950
Devar — 9448936795
Anand — 9902600722
PVenkateswara Rao — 9986115861

AE-W-9 28/04/2014

GKVK Road, Thindlu :- Ward no 9.

Dt — 09-05-2014

Workdone

1) Transportation
2) Rewinding of pumpset
3) ~~10 HP~~ & 12.5 HP motors
4) starter & rototer.
5) upper flange.
6) Lower & Carbon housing.
7) Thrust bearing block assembly.
8) oil seal steel bush & Guide value.
9) Impeller shell
10) DO Bearing.
11) pump shaft, Non return value.
12) Cable guard
13) Brass-filter.
14) Overhauling & painting
15) Labour charge.

ಧನ್ಯವಾದಗಳು

ತಮ್ಮವಿಶ್ವಾಸಿ.

Raghavendra.

9880673571
9437844900
9448936795
9900213950

Dr. W-9 · 9/05/2014

Thindlu AK colony :- ward no : 9

Dt. 12/05/14

Workdone :-

1) Bsan filter.
2) Overhousing & painting.
3) Insulation.
4) pump shaft, non return value.
5) Cable guard.
6) Impeller shell
7) Discharge outlet Bearing, Do steel bush.
8) oil seal steel bush, Guide value.
9) carbon & lower housing.
10) Thrust bearing block assembly.
11) upper flange.
12) ~~10 HP~~ & 12.5 HP motor.
13) starter & rotor.
14) Transportation & labour charge.

Kumar. V 9035618071.

Kalyan chandra 9905008966

N. G. [illegible] 9742337163

G. Kalyan Shankar. 9849444102

12/05/2014

Anjanya layout :- Ward no 9.

3/5/2017

1) Transportation of machineries.
2) Labours charge
3) Rewinding of submersible pumpset ~~pair~~
4) ~~10HP~~ & 12.5Hp motor.
5) starter & Rotor.
6) upper flange
7) lower & carbon housing.
8) Thrust bearing block assembly.
9) oil seal steel bush. , Quick valve.
10) Impeller shell
11) DO Bearing , DO steel bush.
12) pump shaft , NRV
13) Cable guard , Foam filter.
14) overhauling & painting.
15) Insulation.

ಎಲ್ಲರ .ಆ

Yours

ಇಂತಿ ನಿ. ಆ.

Rishi Rakatha.

7899993596

9900504300

9035618074

9741476043

30/5/17

Bullet Krishnappa layout near Dr. house :- Ward no 9.

Dr 13/06/2018

1) 10 HP & ~~12.5~~ HP motor.
2) Transportion of machineries.
3) Rewinding of submersible pumpset
4) starters and Rotor
5) upper flange
6) Carbon & lower housing
7) Thrust bearing
8) oil seal steel bush, Guide valve
9) Impeller shell.
10) DO ~~rubber~~ bearing, DO steel bush.
11) pump shaft, NRV
12) cable guard
13) Brass - filter.
14) Insulation.
15) Over hauling & painting
16) labour charge.

Ramachandra

ಅಶೋಕ

ಕಿರಣ್.

9880460498

9535566799

9945008996

9448315328

T. M. Ramaswamy

Dr
13/06/2018
Dr. W-9

BEL - 1st Block :- Ward no 9.

Dt 26/06/2014

1) Insulation.
2) Overhauling & painting
3) Brass filter.
4) starter & rotaters
5) Transportation of machineries.
6) Labour charge.
7) Rewinding.
8) ~~10 HP~~ & 12.5 HP motors.
9) Carbon & lower housing.
10) upper flange.
11) Thrust bearing
12) oil seal steel bush, Guide valve
13) Impeller shell.
14) DO Bearing, DO steel bush
15) Pump shaft, NRV
16) ~~Brass~~

Sharma 9845661115
ಶಿವಾನಂದ 8861125174
Shanthi 9620792672.
ಅನಿತಾ 9591732918

26/06/2014

W-09

Dhanalakshmi layout :- Ward no 9.

DT - 14/08/2

Work done :-

1) Transportation of machineries.
2) Labour charge.
3) Rewinding
4) ~~10HP~~ & 12.5HP motors.
5) starter & Rotor.
6) upper flange.
7) Lower & carbon housing.
8) Thrust bearing.
9) Oil seal steel bush, Guide value
10) Impelles shell
11) DO Bearing & steel bush.
12) pump shaft, NRV
13) Cable guard.
14) Drain - filter.
15) Overhauling & painting.
16) Insulation.

Gopi
Pillappa
~~Balaji Rao~~
Dilipkao

9900504300
9060983683
23643503.
23645451

14/08/2014
AE - W-9

Doddabommasandra near lake :- Ward no 9.

Dt. 24/10/2014

1) Transportation of machineries.
2) Labour charges.
3) Rewinding
4) 10HP & 12.5HP motors.
5) starters and Rotors.
6) Upper } large
7) Lower & ~~upper housing~~ carbon housing.
8) Thrust bearing
9) oil seal steel bush, Guide value..
10) Impeller shell
11) DO Bearing, steel bush.
12) pump shafts, NRV
13) Cable guard
14) Bilge filter
15) Insulation.

ವೀರಭದ್ರ

VeeraBhadrappa

ಇಇ

ಎಂಜಿನಿಯರ್

9986555520

9880917316

8904664699

9902828359

ಇಇ, ಡ್ರೈನೇಜ್ ವಿಭಾಗ

24/10/2014

Basava Samithi - near Jagdish house :- Ward no 9

Dt. 22/09/2014

Work done:-

1) Insulation.
2) overhauling & pointing
3) Brass filter.
4) Cable guard
5) pump shaft & NRV
6) DO Bearing, steel bush
7) Impeller shell
8) oil seal steel bush, Quick valve
9) Thrust bearing
10) Carbon & lower housing
11) upper flange.
12) Starter & Potor.
13) ~~HP~~ & 12.5HP motor
14) Rewinding
15) Labour charges.

9880460498

9535566799

Pradeep.

9060983683

9535104515

Dr.-Wrks

22/09/2014

Virupakshapura near ganagodan :- Ward no-9.

Dt-10/11/2014

1) Bran-filter.
2) overhauling & painting.
3) Insulation.
4) pump shaft, NRV
5) Cable guard
6) Impeller shell
7) DO Bearing, DO steel bush.
8) oilseal steel bush, Guide valve.
9) Thrust bearing.
10) Carbon & lower housing.
11) upper flange.
12) starter & Rotor.
13) 10HP & 12.5HP motors.
14) labour charge & Transportation.
15) Rewinding.

ನಾಗರಾಜ್ 9844300388
Mangalore 9743268959
Chikkodi 9972987050
Belgaum 9035496649

10/11/2014
AE, W-09, Mangalore

Virupakshapura Maramma Temple.

Dt:- 16/12/2014

Workdone:-

1) Transportation of machineries.
2) Labour charges.
3) Rewinding of
4) 10 HP & 12.5 HP motor
5) starter & Rotor.
6) upper flange
7) Lower & casbon housing
8) Thrust bearing
9) oil seal steel bush, Guide valve
10) Impelle shell
11) DO Bearing, DO steel bush.
12) pump shafts, NRV
13) Cable guard
14) Bran-filter.

Grade copper wire with flexible copper conductor confirming to table 3 clause of IS.

9743673950

9786552823

9743673950

9743208959

16/12/2014 Wednesday